ASBESTOS ASSE SURVEY

H-K Building 15

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/28/89 Inspector: MARK VOTH Building Number: 15

Building Name: OLD KEG WASHING

SEATTLE, WASHINGTON 98134

Building Type: KEGGING Year Constructed: 1940

********* AREA HUMBER: 01 AREA DESCRIPTION: 1st Floor			AREA AVERAGE	x .	********					
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&H CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL
along north wall-at ceiling	00-356344	30%	wrapped cardboard/paper pipe	OHA	64 ft. 4 in. 0.D.	DW	23 111	\$571	\$357	\$928
along south wall-at ceiling	00-356344	30%	wrapped cardboard/paper pipe	AMO	80 ft. 4 in. O.D.	DW	23 111	\$714	\$446	\$1,160
above keg line-along ceiling	00-356351	30%	pipe covering	OMA	143 ft. 4 in. O.D.	HPS/R	23 111	\$1,276	\$798	\$2,074
northwest stairwell-along ceiling	00-356351		pipe covering	AHO	17 ft. 6 in. 0.0.	HPS/R	23 111	\$221	\$138	\$359
near southeast corner-at keg line	00-356351	30%	pipe covering	AHO	44 ft. 4 in. O.D.	HPS/R	23 111	\$392	\$246	8638
along north row of columns-at ceiling	00-356351		pipe covering	AHO	63 ft. 4 in. 0.D.	HPS/R	23 111	\$562	\$352	\$914
northwest corner-at ceiling	00-356351	30%	pipe covering	OHA	8 ft. 6 in. 0.D.	HPS/R	23 111	\$104	\$65	\$169
near west wall-along ceiling	00-356351	30%	pipe covering	OMA	70 ft. 6 in. 0.D.	HPS/R	23 111	\$909	\$568	\$1,477
along south wall-at ceiling	04-356345		mjp on wrapped cardboard/paper	AHO	5 4 in. O.D.	DW	23 111	\$140	\$78	\$218
along north wall-at ceiling	04-356345	40%	mjp on wrapped cardboard/paper	AMO	7 4 in. O.D.	DW	23 111	\$197	\$109	\$306
	04-356346	40%] ''				23 111			
	04-356347	40%					23 111			
northwest corner-at ceiling	05-356348	7%	mjp on non-suspect pipe cover	OHA	2 4 in. O.D.	DW	23 111	\$56	\$31 1	\$87
near west wall-along ceiling	05-356348		mjp on non-suspect pipe cover	OMA	3 4 in. O.D.	DW	23 111	\$84	\$47	\$131
	05-356349	10%	. , , ,				23 111			
•	05-356350	10%					23 111			
near southeast corner-at keg line	06-356352	3%	mjp on pipe covering	OHA	4 4 in. O.D.	HPS/R	23 111	\$112	\$62	\$174
northwest corner-at ceiling	06-356352	3%	mjp on pipe covering	OMA	2 6 in. O.D.	HPS/R	23 111	\$77	\$45	\$122
above keg line-along ceiling	06-356352		mjp on pipe covering	AMO	14 4 in. 0.D.	HPS/R	23 111	\$393	\$219	\$612
above keg line-along ceiling	06-356352	3%	mjp on pipe covering	OMA	2 6 in. O.D.	HPS/R	23 111	\$77	\$45	\$122
along north row of columns-at ceiling	06-356352		mjp on pipe covering	OMA	2 4 in. O.D.	HPS/R	23 111	\$56	\$31	\$87
near west wall-along ceiling	06-356352		mjp on pipe covering	AHO	1 6 in. O.D.	HPS/R	23 111	\$39	\$23	\$62
	06-356353	10%					23 111			
	06-356354	10%					23 111			
AREA COMMENTS	<u> </u>				Γ	A # 01	TOTAL	\$5,980	\$3,660	\$9,640

The materials are in good condition with minor contact and water damage. The materials are approximately 3. to 12' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, glove bag removal procedures are recommended. This appears to be a low traffic area.

r							-				
١	*******	AREA NUMBER: 02	AREA DESCRIPTION	4: 2nd Floor	AREA AVERAGE % ASBESTOS: 25%	*****	ł				
L											
							•				
			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		<del></del>						
	1		DAME! F	1	_						

	LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	PTITHAUD	UNITS OF MEASURE	PIPE ID	EXP POT	PL		REPLACEMENT COSTS	TOTAL COSTS
north	S electrical panel-at heat exchange wall-near stairs S electrical panel-heat exchanger		30%	pipe covering wrapped cardboard/paper pipe boiler/tank insulation	OMA OMA OMB	12 f	t. 4 in. 0. t. 4 in. 0. q.ft.		38	111 111 111	\$107	\$95 \$67 \$4,368	\$247 \$174 \$9,820

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 38

06/09/89

ASBESTOS ASSEL SURVEY

H-K Building #: 15

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/28/89 Inspector: MARK VOTH Building Number: 15

Building Name: OLD KEG WASHING

SEATTLE, WASHINGTON 98134

Building Type: KEGGING

Year Constructed: 1940

near S electrical panel-at heat exchange	01-356334 01-356335 02-356337 02-356338 02-356339 03-356341	10% 10%	mjp on pipe covering	OHA OHA	2 4 in. 0.0. 3 4 in. 0.0.	HÞS/R D <b>u</b>	38 111 38 111 38 111 38 111 38 111	\$56 \$84	\$31 \$47	\$87 \$131
	03-356342 03-356343	40% 40%					38 111 38 111			

AREA COMMENTS

AREA # 02 TOTAL \$5,851 \$4,608 \$10,459

The materials are in fair condition with minor contact and water damage. The materials are approximately 1' to 10' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a low traffic area.

BUILDING # 15	TOTAL	\$11,831	\$8,268	\$20,099

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 39

06/09/89